

IX Amplifier Series 1.0.167 Release Notes

Firmware update for IX series amplifiers for use with SONICUE 1.5.1 patch.

IX series amplifiers must be connected to mains power for a firmware update, won't work on PoE.

Note: the firmware update is not completely done when OMNEO FWUT shows "finished", as there might be updates to the amp boards. Watch the status LEDs on the front, as long as they spin in orange, FW update is still in progress.

Firmware Update via OMNEO Firmware Upload Tool

IX Series amplifier require the OMNEO Firmware Upload Tool 2025-1009

The OMNEO firmware upload tool is a separate app for update of all OMNEO devices within SONICUE. It is part of a SONICUE release package (i.e., SONICUE1.5.1.zip).

1. Install the OMNEO FWUT
2. Execute the device firmware .msi (e.g. IX...msi) – this will install the device's firmware package to the FWUT
3. Connect the device (e.g. IPX amplifier) to your PC/ network and start the app, the device will be displayed
4. Select the device and then firmware version you want to upload
5. Click start
6. Wait until the green bar is all on the right side and State shows: Finished